

P754 – Textured Black



Product Description

P754 is a textured single component black meticulously formulated to replicate the authentic texture of plastic surfaces.

This product restores the original appearance of plastic components to their factory-like aspect, and exhibits excellent adhesion without the need for additional adhesion promoters to plastic substrate.

Adjustments can be made to the coarseness desired by changing the dilution ratio % as described below.

P754 may serve as a primer in conjunction with HYMAX solvent-borne coatings after light scuffing with Scotch Brite.

However, P754 should not be topcoated with Hydrobase.

Extra Comments

No additional top-coating is necessary with P754, as it boasts good resistance to both UV rays and chemical exposure.


Product Application



Scuff surface with a fine pad soaked in GenClean degreaser.




Wipe-on with GenClean degreaser and then wipe-off promptly while the degreaser remains wet on the panel.



	P754	HYMAX Thinner
For coarse texture	100%	0%
For fine texture	100%	40%

Apply the percentage of thinner you need (0 - 40%) based on your texture requirement.




HVLP 1.6 – 1.8 mm.
3.0 – 3.5 bar.

Disclaimer: Users assume full responsibility for any consequences resulting from the incorrect usage of our products.

P754 – Textured Black



2- 3 medium coats of P754.



Between coats, flash off for 5 minutes.



Wear suitable protection and for more information on safety, check the product's Safety Data Sheet.

Product Characteristics

VOC(2004/42/EC):

2004/42/EC IIB (e) (840)656. The EU limit value for this product (product category IIB. e) in ready to use form is max 840g/l. The VOC content of this product in ready to use form is max. 656g/l.

Specific Gravity:

1.05 kg/cm³.

Flash Point:

25°C (86 °F).

Solid Content:

33.1 % by weight.

Coverage:

5-6 m²/l (theoretical).

SDS:

Refer to the Safety Data Sheet.

Shelf life:

18 months.

Disclaimer: Users assume full responsibility for any consequences resulting from the incorrect usage of our products.